


Product Discontinuation Notices

Issue Date
May 15th, 2026



[Final order entry date]
The end of May 2026

[Date of The Last Shipping]
The end of May 2026

[Scheduled date of maintenance close]
The end of May 2026

- [Caution on recommended replacement]**
- ACE 4 license dongles can be used as a replacement for customers using ACE 3.7 or 3.8. End of support for ACE 4.4 and older was communicated when ACE 4.6 was released.
 - V+ and eV+ 2.1 licenses being discontinued are no longer required in eV+ 2.4

[Difference from discontinued product]

Recommended replacement Model	Body Color	Dimen- sions	Wire connection	Mounting Dimensions	Charac- teristics	Operation ratings	Operation methods
ACE 4.X Licenses	**	**	**	**	**	**	**

- ** : Compatible
- * : The change is a little/Almost compatible
- : Not compatible
- : No corresponding specification

[Product Discontinuation and recommended replacement]

Product discontinuation	Description	Recommended Replacement	Description
01056-030	Bundle, ACE Sight, Version 3.0, Software Only	20410-000	Robot Vision Manager
09187-000	Bundle, Software, ACE PackXpert	20409-000	PackManager
09187-010	Bundle, ACE PackXpert w/ACE Sight	20433-000	PackManager + Robot Vision Manager
01056-800	License, Software, ACE Sight 2.x	No Recommended Replacement	
01056-806	License, S/W Option, ACE Sight, Color	No Recommended Replacement	
01056-830	License, Software, ACE Sight 3	No Recommended Replacement	
09187-800	License, ACE SW, PackXpert	No Recommended Replacement	
09287-000	License, ACE SW, Camera	No Recommended Replacement	
09287-010	License, ACE SW, Controller	No Recommended Replacement	
09287-020	License, ACE SW, OPC Server	No Recommended Replacement	
09287-030	License, ACE SW, OPC Client	No Recommended Replacement	
09287-040	License, ACE SW, Color	No Recommended Replacement	
09287-070	License, ACE, UI Builder Option	No Recommended Replacement	

Product discontinuation	Description	Recommended Replacement	Description
09287-080	License, ACE SW, Emulator	No Recommended Replacement	
09961-00013	License, Enhanced Trajectory Control	No Recommended Replacement	
09965-00034	LIC,V+ VERSION 15	No Recommended Replacement	
09966-040	License, V+ Version 16	No Recommended Replacement	
09966-042	License, PLC Client Application, for Adept Controller	No Recommended Replacement	
09967-048	License, Three Adept Robots	No Recommended Replacement	

Specifications and prices in this product news are as of the issue date and are subject to change without notice. Only main changes in specifications are described in this document. Please be sure to read the relevant catalogs, datasheets, product specifications, instructions, and manuals for precautions and necessary information when using products. The information on the recommended substitute products from other companies is what our company is aware of as of the issuance of this notice. Regarding the end of production timing for the recommended alternative product, the possibility of continuing supply, the specifications, compatibility, and others, as well as other details, please inquire with your business partner and make your own decision at your company on whether to adopt the recommended alternative product.